

# Bellamy Surveying and Consultancy Services Ltd



## Asbestos Re-Inspection Survey for

CEVA Logistics

at

Shed 1 Ceva Logistics  
B&Q Distribution Ct  
Burton Road, Burton Upon Trent  
DE14 3EG  
(Asbestos Management 2012)

P/2012/00920

REVISED

Received 01/02/13



Project Number: 20461/12KB

Printed: 09/05/2012 By: Bellamy Surveying and Consultancy Services Ltd. Using Multibase software.



# Bellamy Surveying and Consultancy Services Ltd

## Names and Addresses

---

Client Name:

**CEVA Logistics**

CEVA House  
Excelsior Road  
Ashby de la Zouch  
Leicestershire  
LE65 1NU

Contact: Richard Milne

Phone: 01530 568527 Fax: 01530 568951

Instructing Party:

**CEVA Logistics**

CEVA House  
Excelsior Road  
Ashby de la Zouch  
Leicestershire  
LE65 1NU

Contact: Richard Milne

Phone: 01530 568527 Fax: 01530 568951

Site Full Name:

**Shed 1 Ceva Logistics**

B&Q Distribution Ct  
Burton Road, Burton Upon Trent  
DE14 3EG  
(Asbestos Management 2012)

Contact: Rob Clarke (Facilities Manager)

Phone: 07717 863553 Fax:

Report Author:

**Bellamy Surveying and Consultancy Services Ltd**

Cannon House, 438 Baddow Road  
Chelmsford, Essex CM2 9RB

Contact: Kevin Bellamy Director

Phone: 01245 478333 Fax: 01245 478266

Bellamy Surveying and Consultancy Services Ltd	Project Number:	20461/12KB
	Survey Date:	31 January 2012
	Printed On:	09 May 2012
	Page:	Page 1 of 1

# TABLE OF CONTENTS

SECTION 1	Executive Summary
SECTION 2	Asbestos Register
SECTION 3	Survey Objectives
SECTION 4	Survey Techniques
SECTION 5	Survey Caveat
SECTION 6	Survey Notes
SECTION 7	Material Assessment (Photo Small)
SECTION 8	Material Assessment (History)
SECTION 9	Survey Recommendations
SECTION 10	Bulk Identification Report

# SECTION ONE

## EXECUTIVE SUMMARY

# Bellamy Surveying and Consultancy Services Ltd

## Executive Summary

---

### General Information:

Bellamy Surveying and Consultancy Services Ltd were instructed by CEVA Logistics to carry out an Asbestos Re-Inspection Survey to inspect for the presence of asbestos containing materials (ACMs) at the following site:

Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Branston, Burton Upon Trent, DE14 3EG

The Re-Inspection was carried out on 31st January 2012 by Kevin Bellamy

Within the scope of the survey, asbestos materials have been identified or strongly presumed / presumed. The incidences of asbestos containing materials (ACMs) are summarised below.

Sample 2. Refers to Skylights containing asbestos gaskets.

Sample 3. Refers to Corrugated Roofing Sheets.

Sample 6. Refers to Vented Outlets at Roof Level containing asbestos gaskets.

Sample 8. Refers to Bitumen Felt Coverings.

Sample 11. Refers to poor condition asbestos board.

For identification of materials removed for bulk sampling analysis, please refer to the individual sample data sheets.

Any asbestos materials remaining in the building must be encapsulated and/or labelled using recognised asbestos management materials and identification labels. A management system must be implemented to assess and manage the risks associated with asbestos materials at site. It is strongly advised that all staff and visiting contractors familiarise themselves with the asbestos management plan to ensure that asbestos materials at site are not disturbed or damaged. Refer to the Asbestos Acknowledgement Form and Asbestos Work Record.

We recommend a refurbishment & demolition survey takes place prior to any future refurbishment or demolition works.

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics. B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Site Description:</b>	Page 1 of 1

# SECTION TWO

## ASBESTOS REGISTER

# Asbestos Register

Site Name: Shed 1 Ceva Logistics

Project Number: 20461/12KB

Location	Product type and name		Extent	Accessibility	Condition	Surface treatment	Asbestos Type	Sample	Sample no	Material Risk Score	Priority Risk Score	Total Score
Ground floor, Electrical Room	Asbestos Insulating Board	Board	60m <sup>2</sup> Approx	Medium Accessibility	High damage	Unsealed AIB	Amosite & Chrysotile	Strongly Presumed	Sample 11	9		N/A
General through out, Warehouse	Ropes and woven textiles	Skylight	Representative Skylight Reference	Difficult Accessibility	No visible damage	Enclosed sprays and lagging	Chrysotile	Presumed	Sample 2	4		N/A
Roof level, Warehouse	Asbestos cement	Roofing Sheets	Representative Roofing Sheet Reference	Difficult Accessibility	Good condition	Asbestos cement sheets etc	Chrysotile	Identified	Sample 3	3		N/A
Roof level, External	Ropes and woven textiles	Vent Outlet	Representative Vented Outlet	Difficult Accessibility	No visible damage	Enclosed sprays and lagging	Chrysotile	Presumed	Sample 6	4		N/A
Ground floor, Warehouse	Asbestos Reinforced Composites	Felt / Bitumen	Representative Felt Bitumen Reference	Easy Accessibility	Low damage	Composite asbestos materials	Chrysotile	Identified	Sample 8	3		N/A

MATERIAL SCORES ABOVE 10 HAVE HIGH POTENTIAL TO RELEASE FIBRES



# SECTION THREE

## SURVEY OBJECTIVES



# Bellamy Surveying and Consultancy Services Ltd

## Survey Objectives

---

- 1 Instructions were received from Rob Clarke Ceva Logistics to provide an Asbestos Re-Inspection Survey report in strict accordance with Asbestos: The Survey Guide HSG 264 for Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Branston, Burton Upon Trent, DE14 3EG in a database format, indicating areas containing identified and suspected asbestos based materials, including photographic records of asbestos occurrences where possible.
- 2 To carry out a survey to ascertain the presence and condition of asbestos based materials identified in type 2 asbestos survey May 2004. Regular asbestos management/re-inspections have taken place since, on 14th November 2007, 4th November 2008, 10th December 2009 and 27th Jan 2011.
- 3 To include a risk assessment for each individual Sample.  
NADIS (No asbestos detected in sample)  
ACM (Asbestos Containing Material)

- 4 In accordance with Asbestos: The Survey Guide (HSG264)  
  
A Management Survey (Formerly Type 2 Asbestos Survey)

The management survey is the standard survey. Its purpose is to locate, as far as reasonably practicable, the presence and extent of any suspect asbestos containing material (ACMs) in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.

Samples from each type of suspect ACM found are collected and analysed to confirm or refute the surveyor's judgement. If the material sampled is found to contain asbestos, other similar homogeneous materials used in the same way in the building can be strongly presumed to contain asbestos. Less homogeneous materials will require a greater number of samples. The number should be sufficient for the surveyor to make an assessment of whether asbestos is or is not present.

- 5 Surveying Company Details.

Bellamy Surveying and Consultancy Services Ltd  
Cannon House  
438 Baddow Road  
Chelmsford  
Essex CM2 9RB

Survey carried out by Kevin Bellamy

Report produced by Natalie Parry

Signed.

- 6 Re-inspection Date. 31st January 2012

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Survey Objectives:</b>	Page 1 of 1

# SECTION FOUR

## SURVEY TECHNIQUES

# Bellamy Surveying and Consultancy Services Ltd

## Survey Techniques

---

- 1 Photographs were taken at all of the sample locations (unless otherwise stated).

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Survey Technique:</b>	Page 1 of 1

# SECTION FIVE

## SURVEY CAVEAT

# Bellamy Surveying and Consultancy Services Ltd

## Survey Caveat

---

- 1 It should be clearly understood that an asbestos survey or re-inspection survey cannot guarantee to identify all asbestos materials present within a property. Bellamy Surveying and Consultancy Services Ltd will accept no responsibility for any financial loss that may arise from asbestos materials present within a property surveyed.
- 2 Management Surveys and Re-inspection Surveys will provide only a limited inspection of pipework and other heating or supply services concealed by overlying non-asbestos insulations. Inspection of pipework has been restricted primarily to the insulation visible. The presence of debris to pipework, which is not readily visible or would require the removal and subsequent replacement of non-asbestos insulation has been considered outside the scope of this survey.
- 3 Asbestos Management, Refurbishment and Demolition surveys or Re-inspection surveys will not include lift shafts/waiter shafts or any live plant machinery / facility or similar, that would require the attendance of a specialist engineer, i.e. boiler units, air conditioning units and plant.
- 4 Any lift shafts / waiter shafts present and/or plant machinery will only be included in the survey with the attendance of a specialist engineer.
- 5 Samples have not been taken where the act of sampling would endanger the surveyor, occupiers, tenants and visitors or effect the functional integrity of the item or the building's weather tightness or security. Where materials containing asbestos products are presumed or strongly presumed to be evident and where sampling was not possible, photographic samples are provided of such materials i.e. mechanical plant and building items etc. to make clients, contractors, staff and visitors aware, e.g. electrical fuse guards, gaskets, fire doors, glazing, skylights, power plant, etc.
- 6 The survey took part to all areas of the Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Branston, Burton Upon Trent, DE14 3EG where access was arranged by Julie Bridgett, Ceva Logistics and provided by Rob Clarke (Facilities Manager).  
  
All areas were accessed.  
  
Any areas of 'No Access' should be presumed to contain asbestos products until access can be gained and the material / area surveyed.
- 7 Individual analysis and risk assessments have been applied to each representative sample removed for laboratory analysis. It is the responsibility of the licensed asbestos removal contractors', refurbishment contractors' or demolition contractor to satisfy themselves the extent of any asbestos materials or presumed asbestos materials identified at site.
- 8 In some instances photographic references are made of materials at roof level i.e. soffits fascias and flue pipes, flue pipe cowlings etc, that would require an access scaffold or elevated platform for access for sampling purposes. Contractors are to be aware that items and materials at roof or roof eaves level may be asbestos.

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Survey Caveat:</b>	Page 1 of 1

# SECTION SIX

## SURVEY NOTES

# Bellamy Surveying and Consultancy Services Ltd

## Survey Notes

---

- 1 Whilst every effort was made to locate the asbestos based products i.e. ceiling panels, wall partitions and insulation materials, which may have been constructed from asbestos boarding or asbestos based materials, none other than those detailed were found. Some may have been missed due to repairs, refurbishment works and alterations etc, where false and other finishes have been applied or where different specifications (including a possible mixture of asbestos and non-asbestos) panels have been used in the same area. Only by sampling each panel or item would the composition of all the materials be known. This was clearly not practical in terms of cost or time.
- 2 No air monitoring was carried out whilst the survey was undertaken, therefore care was taken not to cause disturbance of fibre or contamination of clean surfaces.
- 3 This report has been written with reference to the various Guidance Notes current at the date of this report, i.e. HSG264, and describes circumstances at the site on the date the investigation took place.
- 4 Where similar items exist in the building, only one or two samples have been taken to ascertain the material content. It was assumed that similar products were of the same material. Only random sampling or assessment was carried out.
- 5 Any person undertaking work within the buildings should be told of the presence of asbestos. This briefing also applies to any other person associated with the site, including staff, sub-contractors and others.
- 6 Any diagrams provided / attached to this report are not to scale and are illustrative only to indicate approximate locations. The descriptions used are for location identification purposes
- 7 All the recommendations described in this report are based upon assumptions made after consideration of the type of material, condition of the material, its location, analysis result and type of use the area is thought to be subjected to. However, statutory authorities or others, could require amendments based on local knowledge, change in legislation, change in use or indeed, other conditions of criteria.
- 8 Equipment, machinery, ducting etc were not moved, opened up or examined for the purpose of this investigation.
- 9 This asbestos report is not to be used as an addendum or attachment or part of a tender document for the purposes of submitting quotations for any asbestos abatement works.

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Survey Objectives:</b>	Page 1 of 1

# SECTION SEVEN

## SAMPLE INSPECTION RECORD



# Bellamy Surveying and Consultancy Services Ltd

## Sample Inspection Record

Sorted by: Location ID

Site Address: Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos Management 2012)

Client Name: CEVA Logistics

Project Number: 20461/12KB

Area/ Floor/ Room/ Product: Ceva Shed 1: General through out: Warehouse: Skylight

Inspection Date: 31/01/2012 Next Inspection: 30/01/2013 Survey Type: RI

Location ID: 4513 Location Ref: Sample 2 Product Type: Ropes and woven textiles



Action:  
Do Not Disturb - Contractors to be Aware

Material Comments:  
A photographic reference was made to the roof skylights within Shed 1, presumed to contain asbestos products, i.e gaskets and seals. Skylights still in place during management visit 31/01/2012. Please note vented roof outlets may also contain asbestos.

Damage: No visible damage

Treatment: Enclosed sprays and lagging

Asbestos Type: Chrysotile

Identification: Presumed

Quantity: Representative Skylight Reference

Material Risk Score: 4 Material Risk Band: Very Low Risk Priority Risk Score: N/A

Area/ Floor/ Room/ Product: Ceva Shed 1: Roof level: Warehouse: Roofing Sheets

Inspection Date: 31/01/2012 Next Inspection: 30/01/2013 Survey Type: RI

Location ID: 4514 Location Ref: Sample 3 Product Type: Asbestos cement



Action:  
Do Not Disturb - Contractors to be Aware

Material Comments:  
A photographic reference was made to the roofing sheets internally within Shed 1 warehouse previously identified as containing asbestos products. Noted 31.1.2012.

Damage: Good condition

Treatment: Asbestos cement sheets etc

Asbestos Type: Chrysotile

Identification: Identified

Quantity: Representative Roofing Sheet Reference

Material Risk Score: 3 Material Risk Band: Very Low Risk Priority Risk Score: N/A



# Bellamy Surveying and Consultancy Services Ltd

## Sample Inspection Record

Sorted by: Location ID

Site Address:

Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos Management 2012)

Client Name:

CEVA Logistics

Project Number:

20461/12KB

Area/ Floor/ Room/ Product: Ceva Shed 1: Roof level: External: Vent Outlet

Inspection Date: 31/01/2012

Next Inspection: 30/01/2013

Survey Type: RI

Location ID: 4517

Location Ref: Sample 6

Product Type: Ropes and woven textiles



**Action:**

Do Not Disturb - Contractors to be Aware

Damage: No visible damage

Treatment: Enclosed sprays and lagging

**Material Comments:**

A photographic reference was made to the vented outlets at roof level, presumed to contain asbestos products, i.e gaskets and seals. Still in place during management visit 31/01/2012.

Asbestos Type: Chrysotile

Identification: Presumed

Quantity: Representative Vented Outlet

Material Risk Score: 4

Material Risk Band: Very Low Risk

Priority Risk Score: N/A

Area/ Floor/ Room/ Product: Ceva Shed 1: Ground floor: Warehouse: Felt / Bitumen

Inspection Date: 31/01/2012

Next Inspection: 30/01/2013

Survey Type: RI

Location ID: 4518

Location Ref: Sample 8

Product Type: Asbestos Reinforced Composites



**Action:**

Warning Labels Applied. Do Not Disturb

Damage: Low damage

Treatment: Composite asbestos materials

**Material Comments:**

A photographic reference was made to the felt bitumen coverings within the canopy shelter of Shed 1 identified as asbestos products still in place during management visit 31/01/2012.

Asbestos Type: Chrysotile

Identification: Identified

Quantity: Representative Felt Bitumen Reference

Material Risk Score: 3

Material Risk Band: Very Low Risk

Priority Risk Score: N/A

Area/ Floor/ Room/ Product: Ceva Shed 1: Ground floor: Electrical Room: Board

Inspection Date: 31/01/2012

Next Inspection: 31/01/2013

Survey Type: RI

Location ID: 4519

Location Ref: Sample 11

Product Type: Asbestos Insulating Board



**Action:**

Warning Labels Applied. Do Not Disturb

Damage: High damage

Treatment: Unsealed AIB

**Material Comments:**

A photographic reference was made to the asbestos board within the electrical stores to the front of Shed 1. Board is in very poor condition and requires removal by licensed contractors and the electrical stores environmentally cleaned.

Asbestos Type: Amosite & Chrysotile

Identification: Strongly Presumed

Quantity: 60m<sup>2</sup> Approx

Material Risk Score: 9

Material Risk Band: Medium Risk

Priority Risk Score: N/A

# SECTION EIGHT

## MATERIAL ASSESSMENT HISTORY

# Material Assessment History

Site Name Shed 1 Ceva Logistics  
 Project Number 20461/12KB

Sample Date	Location Ref	Location ID	Area	Floor	Room	Component	Asbestos Type	Material Risk Score	Comments	Action	Survey Type
27/01/11	Sample 2	4513	Ceva Shed 1	General through out	Warehouse	Ropes and woven textiles	Chrysotile	4	A photographic reference was made to the roof skylights within Shed 1, presumed to contain asbestos products, i.e gaskets and seals.	Contractors and Staff to be Aware	RI
31/01/12	Sample 2	4513	Ceva Shed 1	General through out	Warehouse	Ropes and woven textiles	Chrysotile	4	A photographic reference was made to the roof skylights within Shed 1, presumed to contain asbestos products, i.e gaskets and seals. Skylights still in place during management visit 31/01/2012. Please note vented roof outlets may also contain asbestos.	Do Not Disturb - Contractors to be Aware	RI

2x Inspection(s) for Sample Number: Sample 2

27/01/11	Sample 3	4514	Ceva Shed 1	Roof level	Warehouse	Asbestos cement	Chrysotile	3	A photographic reference was made to the roofing sheets internally within Shed 1 warehouse previously identified as containing asbestos products.	Contractors and Staff to be Aware	RI
31/01/12	Sample 3	4514	Ceva Shed 1	Roof level	Warehouse	Asbestos cement	Chrysotile	3	A photographic reference was made to the roofing sheets internally within Shed 1 warehouse previously identified as containing asbestos products. Noted 31.1.2012.	Do Not Disturb - Contractors to be Aware	RI

2x Inspection(s) for Sample Number: Sample 3



# Material Assessment History

Site Name Shed 1 Ceva Logistics  
 Project Number 20461/12KB

Sample Date	Location Ref	Location ID	Area	Floor	Room	Component	Asbestos Type	Material Risk Score	Comments	Action	Survey Type
27/01/11	Sample 6	4517	Ceva Shed 1	Roof level	External	Ropes and woven textiles	Chrysotile	4	A photographic reference was made to the vented outlets at roof level, presumed to contain asbestos products, i.e gaskets and seals. Still in place during management visit 27/01/2011.	Contractors and Staff to be Aware	RI
31/01/12	Sample 6	4517	Ceva Shed 1	Roof level	External	Ropes and woven textiles	Chrysotile	4	A photographic reference was made to the vented outlets at roof level, presumed to contain asbestos products, i.e gaskets and seals. Still in place during management visit 31/01/2012.	Do Not Disturb - Contractors to be Aware	RI
2x Inspection(s) for Sample Number: Sample 6											
27/01/11	Sample 8	4518	Ceva Shed 1	Ground floor	Warehouse	Asbestos Reinforced Composites	Chrysotile	3	A photographic reference was made to the felt bitumen coverings within the canopy shelter of Shed 1 identified as asbestos products still in place during management visit 27/01/2011.	Warning Labels Applied Monitor Annually	RI
31/01/12	Sample 8	4518	Ceva Shed 1	Ground floor	Warehouse	Asbestos Reinforced Composites	Chrysotile	3	A photographic reference was made to the felt bitumen coverings within the canopy shelter of Shed 1 identified as asbestos products still in place during management visit 31/01/2012.	Warning Labels Applied. Do Not Disturb	RI
2x Inspection(s) for Sample Number: Sample 8											



# Material Assessment History

Site Name	Shed 1 Ceva Logistics
Project Number	20461/12KB

Sample Date	Location Ref	Location ID	Area	Floor	Room	Component	Asbestos Type	Material Risk Score	Comments	Action	Survey Type
27/01/11	Sample 11	4519	Ceva Shed 1	Ground floor	Electrical Room	Asbestos Insulating Board	Amosite & Chrysotile	9	A photographic reference was made to the asbestos board within the electrical stores to the front of Shed 1. Board is in very poor condition and requires removal work by licensed contractors and the electrical stores environmentally cleaned.	Removal By Licensed Contractors	RI
31/01/12	Sample 11	4519	Ceva Shed 1	Ground floor	Electrical Room	Asbestos Insulating Board	Amosite & Chrysotile	9	A photographic reference was made to the asbestos board within the electrical stores to the front of Shed 1. Board is in very poor condition and requires removal by licensed contractors and the electrical stores environmentally cleaned.	Warning Labels Applied. Do Not Disturb	RI

2x Inspection(s) for Sample Number: Sample 11



# SECTION NINE

## SURVEY RECOMMENDATIONS

## Survey Recommendations

---

### 1 Material Assessment and Algorithm

The material assessment is an assessment of the condition of the ACM, or the presumed ACM and the likelihood of it releasing fibres in the event of it being disturbed in some way. This material assessment will give a good initial guide to the priority for management, as it will identify the materials which will most readily release airborne fibres if disturbed. However, there are other factors to take into account when prioritising action.

HSG 264 recommends the use of an algorithm chart to carry out the material assessment and contains an example. The algorithm chart is a numerical way of taking into account several influencing factors, giving each factor considered a score. These scores can then be totaled to give a material assessment score. The use of algorithms is not infallible, but the assessment process is clear for all to see, so if discrepancies arise, it should be possible to track back through the assessment process to find the root of the error. The algorithm chart shown in the HSG 264 considers four parameters that determine the risk from ACMs, that is the ability to release fibres if disturbed. These four parameters are:

Product type;  
Extent of damage or deterioration;  
Surface treatment; and  
Asbestos type.

Each of the parameters is scored and added to give a total score between 2 and 12 inclusive:

Materials with scores of 10 or more should be regarded as high risk with a significantly high potential to release fibres if disturbed;

Those with a score between 7 and 9 inclusive are regarded as medium risk / potential;

Materials with a score of 5 and 6 are low risk / potential

Scores of 4 or less are very low risk / potential.

NADIS = No Asbestos Detected in Sample

THE RISK ASSESSMENT INCLUDES A MATERIAL ASSESSMENT.

THE MATERIAL ASSESSMENT LOOKS AT THE TYPE AND CONDITION OF THE ACM AND THE EASE WITH WHICH IT WILL RELEASE FIBRES IF DISTURBED.

The risk assessment can only be carried out with detailed knowledge of all the above. Although a surveyor may have some of the information which will contribute to the risk assessment and may be part of an assessment team, you, as the duty holder under CAR Regulations 2006 are required to make the risk assessment, using the information given in the survey report and your detailed knowledge of the activities carried out within your premises. The risk assessment will form the basis of the management plan, so it is important that it is accurate.

The scores from the material assessment (i.e. the condition of the ACM or presumed ACM) are added to the scores of the priority assessment (the likelihood of disturbance), to give the overall risk assessment. Risk assessment scores for different ACMs can then be compared to develop your action plan. In many circumstances the scores will be similar, making decisions more difficult. For example a boiler house with asbestos pipe work insulation in poor condition may get the same or similar risk assessment score to an office with asbestos insulating board in reasonably good condition. This is simply because the ACM in the boiler house received a higher score than the ACM in the office because the ACM in the boiler house was in poor

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Recommendation:</b>	Page 1 of 5



# Bellamy Surveying and Consultancy Services Ltd

## Survey Recommendations

---

condition. However, the priority assessment for the office will get a higher score than the boiler house since the office is occupied more often. Add the scores together for the material and priority assessments, and you get similar scores. If this is the case then you may decide that the office needs doing first because it is used daily. On the other hand you may decide that the poor condition of the ACM in the boiler house means that it should be done first. If the office was a classroom, the young age of the occupants may be a deciding factor. Algorithms are provided to help you, but will require you to make your own additional judgments.

It may be the case that during the survey no samples were removed for analysis. This may be due to several factors, i.e. restrictive access to certain parts of the building, the building may have been the subject of a major refurbishment throughout, the building may be a new construction. In all cases the judgement to remove samples remains with the surveyor.

- 2 In cases of asbestos management, it is advised and recommended that asbestos management to identified materials is carried out on an annual basis or less, as required in line with the material location and condition.

Asbestos management can include encapsulation and labelling using approved sealing coating and asbestos warning labels and signs.

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos	<b>Printed On:</b>	09 May 2012
		<b>Recommendation:</b>	Page 2 of 5

# Bellamy Surveying and Consultancy Services Ltd

## Material Assessment Algorithm

Sample variable	Score	Examples of scores
Product type (or debris from product)	1	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).
	2	AIB, millboards, other low-density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.
	3	Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.
Extent of damage/deterioration	0	Good condition: no visible damage.
	1	Low damage: a few scratches or surface marks, broken edges on boards, tiles etc.
	2	Medium damage: significant breakage of materials or several small areas where material has been damaged revealing loose asbestos fibres.
	3	High damage or delamination of materials, sprays and thermal insulation. Visible asbestos debris.
Surface treatment	0	Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles.
	1	Enclosed sprays and lagging, AIB (with exposed face painted or encapsulated) asbestos cement sheets etc.
	2	Unsealed AIB, or encapsulated lagging and sprays.
	3	Unsealed lagging and sprays.
Asbestos type	1	Chrysotile.
	2	Amphibole asbestos excluding crocidolite.
	3	Crocidolite.
Total		

Score	Potential to release asbestos fibres
10 or more	High
7 - 9	Medium
5 - 6	Low
4 - less	Very low

Non-asbestos materials have no potential to release asbestos fibres

<b>Client Name:</b>	CEVA Logistics	<b>Project Number:</b>	20461/12KB
		<b>Survey Date:</b>	31 January 2012
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos)	<b>Printed On:</b>	09 May 2012
		<b>Recommendation:</b>	Page 4 of 5

# Bellamy Surveying and Consultancy Services Ltd

## Asbestos Warning Labels

---



Client Name:	CEVA Logistics	Project Number:	20461/12KB
		Survey Date:	31 January 2012
Site Address:	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos)	Printed On:	09 May 2012
		Recommendation:	Page 5 of 5

# SECTION TEN

## BULK IDENTIFICATION REPORT

# Bellamy Surveying and Consultancy Services Ltd

## BULK IDENTIFICATION REPORT

<b>Client:</b>	CEVA Logistics	<b>Date Samples Received:</b>	Between 27/01/2011 and 31/01/2012
<b>Client Address:</b>	CEVA House, Excelsior Road, Ashby de la Zouch, Leicestershire, LE65 1NU	<b>Date Samples Analysed:</b>	
<b>Site Address:</b>	Shed 1 Ceva Logistics, B&Q Distribution Ct, Burton Road, Burton Upon Trent, DE14 3EG, (Asbestos Management 2012)		
<b>F.A.O:</b>	Rob Clarke (Facilities Manager)	<b>Page 1 of 1</b>	

### METHOD STATEMENT:

Samples of material referenced below, have been examined to determine the presence of asbestos fibres, using a method of polarising light microscopy and centre stop dispersion staining, based on the HSG 248, Asbestos: The Analyst's guide for sampling analysis and clearance procedures". NOTE: We cannot be held responsible for the accuracy and competence of samples taken by third parties. Under these circumstances we cannot be held responsible for the interpretation of the results shown.

Location Ref	Location ID	Sample Location	Fibre Type-Quantity
Sample 3	4514	Roof level, Warehouse, Roofing Sheets	Chrysotile Representative Roofing Sheet Reference
Sample 8	4518	Ground floor, Warehouse, Felt / Bitumen	Chrysotile Representative Felt Bitumen Reference

REPORT RAISED BY:

Signed: ..... Print: .....