## **Proposed Replacement of Windows**

## 4 The Yews, Mill Street Rocester, ST14 5LZ

Significant Rot on the rear French doors.



Peeling and exposed beading – damp wood and leaking






## Substandard putty used in installation now hard and cracket and leaking.



Badly manufactured casements on many windows with large gaps



Broken window glazing units due to incorrect fitting and no expansion



